


IDENTITY	DESCRIPT	Lat_Y	Lon_X
HC-5	Bamboo	35.59867	-92.15012
HC-4	Bamboo	35.59830	-92.15021
HC-3	Bamboo	35.59803	-92.15029
HC-6	Bamboo	35.59915	-92.15016
HC-11	Bamboo	35.60507	-92.13721
HC-12	Bamboo	35.60465	-92.13684
HC-13	Bamboo	35.60454	-92.13645
HC-14	Bamboo	35.60449	-92.13626
HC-1	Bamboo	35.59825	-92.15122
HC-2	Bamboo	35.59786	-92.15113
HC-7	Bamboo	35.60017	-92.14914
HC-8	Bamboo	35.59990	-92.14862
HC-9	Bamboo	35.59990	-92.14792
HC-10	Bamboo	35.59984	-92.14765
HC-31	Brush	35.60140	-92.17765
HC-32	Brush	35.60157	-92.17834
HC-19	Brush	35.60774	-92.15141
HC-21	Brush	35.61318	-92.15278
HC-23	Brush	35.61395	-92.15188
HC-24	Brush	35.61443	-92.15103
HC-25	Brush	35.61506	-92.15094
HC-27	Brush	35.61684	-92.15101
FC-17	Brush	35.60255	-92.12442
FC-18	Brush	35.60247	-92.12389
FC-16	Brush	35.60267	-92.12482
HC-26	Brush	35.61649	-92.14964
FC-19	Brush	35.60243	-92.12331
HC-20	Brush	35.60762	-92.15159
HC-28	Brush	35.61911	-92.15153
HC-29	Brush	35.61933	-92.15129
HC-30	Brush	35.61964	-92.15115
HC-22	Brush	35.61346	-92.15237
HC-15	Brush	35.60823	-92.14298
HC-16	Brush	35.60782	-92.14313
HC-18	Brush	35.60772	-92.14529
HC-17	Brush	35.60758	-92.14462



HILL CREEK FISH STRUCTURE



This image is an approximate representation and may not be used as a legal document due to errors in the generation process. Copies of survey plats and shoreline allocation maps may be obtained through the Greers Ferry Lake Project Office. The Corps of Engineers is not responsible for any incorrect information provided in this map.

