


# Greers Ferry Lake



Identity	DESCRIPT	Year	Lat_Y	Lon_X
FC-1	PVC	2009	35.6202*	-92.0817*
FC-10	Mossback	2014	35.6178*	-92.0948*
FC-11	Brush	2014	35.6168*	-92.0962*
FC-12	Brush	2014	35.6172*	-92.0953*
FC-13	Mossback	2014	35.6136*	-92.1097*
FC-14	Mossback	2014	35.6058*	-92.1147*
FC-15	Mossback	2014	35.6057*	-92.1249*
FC-16	PVC	2014	35.6163*	-92.0914*
FC-16	Brush	2015	35.6026*	-92.1248*
FC-17	Mossback	2014	35.6167*	-92.0629*
FC-18	Brush	2015	35.6024*	-92.1238*
FC-19	Brush	2015	35.6024*	-92.1233*
FC-2	Mossback	2009	35.6182*	-92.0946*
FC-20	Brush	2015	35.6025*	-92.1244*
FC-21	PVC	2009	35.6168*	-92.0625*
FC-3	Mossback	2009	35.6171*	-92.1013*
FC-4	PVC	2009	35.6207*	-92.0959*
FC-5	Brush	2009	35.6173*	-92.0957*
FC-6	PVC	2009	35.6201*	-92.0900*
FC-7	Brush	2014	35.6138*	-92.1013*
FC-8	Brush	2014	35.6112*	-92.0993*
FC-9	Mossback	2014	35.6180*	-92.0946*

## Frontier Canyon Fish Structure

This image is an approximate representation and may not be used as a legal document due to errors in the generation process. The Corps of Engineers is not responsible for any incorrect information provided in this map.

